Amendments to the Specification:

Kindly replace the ABSTRACT with the following replacement ABSTRACT:

A method for checking bores in or edges on an object of measurement, and in particular for recognizing burrs. A prepared object of reference is scanned with a distance sensor in correlation with scanning the prepared object of reference with another distance sensor. The measurement signals of the two distance sensors are then compared.